






PAGER


Version 8

M 7.1, 60 km SE of Bobon, PhilippinesOrigin Time: 2021-08-11 17:46:13 UTC (Thu 01:46:13 local) Location: 6.4778° N 126.7160° E Depth: 55.2 km

FOR TSUNAMI INFORMATION, SEE: tsunami.gov



and economic losses. There is a low likelihood of casualties and damage.



Estimated Population Exposed to Earthquake Shaking

127.2°E

ESTIMATED POPULATION EXPOSURE (k=x1000)		1k*	23,018k	13,550k	5,509k	652k	3k	0	0	0
ESTIMATED MODIFIED MERCALLI INTENSITY		I	11-111	IV	V	VI	VII	VIII	IX	X+
PERCEIVED SHAKING		Not felt	Weak	Light	Moderate	Strong	Very Strong	Severe	Violent	Extreme
POTENTIAL DAMAGE	Resistant Structures	None	None	None	V. Light	Light	Moderate	Mod./Heavy	Heavy	V. Heavy
	Vulnerable Structures	None	None	None	Light	Moderate	Mod./Heavy	Heavy	V. Heavy	V. Heavy

^{*}Estimated exposure only includes population within the map area.

Population Exposure

population per 1 sq. km from Landscan

129.9°E

100

Structures 5000 10000

Overall, the population in this region resides in structures that are a mix of vulnerable and earthquake resistant construction. The predominant vulnerable building types are unknown/miscellaneous types and heavy wood frame construction.

Historical Earthquakes

Selected City Exposure

from GeoNames.org

Date	Dist.	Mag.	Max	Shaking
(UTC)	(km)		MMI(#)	Deaths
1987-05-23	219	5.7	VII(70k)	1
1987-05-18	251	6.2	VIII(12k)	1
2002-03-05	281	7.5	VIII(12k)	15

Recent earthquakes in this area have caused secondary hazards such as tsunamis and landslides that might have contributed to losses.

11/ 4.1 ° N Mangarang

PAGER content is automatically generated, and only considers losses due to structural damage. Limitations of input data, shaking estimates, and loss models may add uncertainty.

bold cities appear on map.

MMI City Population VII Bobon V١ Jovellar V١ Lukatan 3k ۷I **Tarragona** 4k V١ Tamisan 3k ۷I San Ignacio 6k V Davao 1,213k I۷ **Butuan** 310k Ш Cagayan de Oro 445k Ш Cebu City 799k Ш lloilo 388k

(k = x1000)